

Service Engineer Site Report

Customer:	Arqiva	Site: Pontop Pike Aggreko Generator
Engineer(s):	Brendan McGuinness	Site Contact: Arqiva Staff
Job Type:	Paint Generator	Serial Number:

Date	Start	Finish	Travel time	Mileage
16.07.19-19.0.19	08.:00	18:00	6hrs	298

Details of work carried out:

Attend site wash down generator using pressure washer, rub down rust areas and treat, apply 1x under coat, apply 2 x Top coat using a 2-coat epoxy paint, clear all waste from site.

Before.



After



Engineer: Brendan McGuinness

Date: 19.07.19